Car for sale

2011 HONDA CRV EX, 65440miles, in excellent condition, no accident. Driven most time in the southern states, no rust. \$11000 OBO.

Tel:3156006152















AR MC	CRU	TRIM	TAFFETA WHITE
0107311510			TECHNICIAN
STGICE 3H56B			10/35/11
ed below, and mark the \square af	ter inspectio	ce manual, owner's manual, n. Put a line through the iten	and service bulletin to do all of the operation if it does not apply to the vehicle.
Before Starting PDI		I. Vehicle Interior (Part 1)	2. Vehicle Exterior (Part 1)
Fill up fuel tank; check fuel fill	door	Release hood and tailgate	Walk-around
Check fuel gauge operation		Check hood and tailgate latch	☐ Check body fit and alignment
Remove exterior protective covering (if vehicle is being prepared for delivery to custor	nor)	operation Remove items from cargo area	Check paint finish for dents, dings, scratches, and blemishes
Wash vehicle thoroughly	ner)	Remove interior protective plasma. Install floor mats	Check hinges, locks, and latches (lubrication and operation)
Check paint finish for dents, d scratches, and blemishes	ings,	Install interior fuse(s) Check childproof locks	Radio Code
		Check seat belts and operation	n
		Remove front seat tags	131/22
		Check brake pedal freeplay an parking brake adjustment	nd 13400